



Directions: To remove rust and grease from equipment, submerge articles to be cleaned in a hot solution containing 10-20 lb. of DEGREASER per 50 gallons of water for 10 minutes. Equipment can also be cleaned by spraying continuously for 10 minutes with a hot DEGREASER solution. After cleaning, rinse thoroughly and coat articles with a light oil.

DEGREASER

**FOR REMOVAL OF RUST
AND GREASE FROM METAL
SURFACES, ENGINE PARTS
AND EQUIPMENT.**

WARNING: Harmful if Swallowed: Corrosive to mouth, throat, esophagus and stomach. **Avoid Breathing Dust or Mists:** Corrosive to mucous membranes of the respiratory tract. **Avoid Eye Contact:** *Corrosive to eyes:* Burns eye tissue, cornea and retina. **Avoid Contact With Skin:** Corrosive to skin, causes severe & rapid burns, destructive to tissues on contact. **PERSONAL PROTECTION:** Wash thoroughly after use. Use with adequate ventilation. Chemical type goggles recommended. Impervious rubber or neoprene gloves recommended. **First Aid: INHALATION-**Get to fresh air. **EYES-**Flush with plenty of water for at least 15 minutes. See a physician. **INGESTION-**Do not induce vomiting. If conscious drink plenty of water. Call a physician or poison control center immediately. **SKIN-**Flush with plenty of water. READ THE MATERIAL SAFETY DATA SHEET (MSDS) BEFORE USING THIS PRODUCT.

KEEP OUT OF REACH OF CHILDREN

The Quality Chemical Company 
VentureTECH
CORPORATION

10720 Lexington Drive • Knoxville, TN 37932
(865) 966-2532 • 1-800-826-4095 • FAX (865) 675-2532

MEMBER
ISSA

HMIS RATING

0	Fire Hazard	0 - None
0	Reactivity	1 - Slight
2	Health Hazard	2 - Moderate
		3 - High
		4 - Severe