



SPECIALLY DEVELOPED FOR RE-CALCULATING CLEANING SYSTEMS REMOVES RUST AND GREASE FROM PARTS AND EQUIPMENT SURFACES HIGHLY ACTIVE / NON-FOAMING / CONCENTRATED CONTAINS TWO CORROSION INHIBITORS.

Directions: To remove rust and grease from parts and equipment, spray continuously for 10 minutes with a hot (150-180° F) cleaner solution containing 1/2 - 3/4 lb POWER OFF. Equipment can also be cleaned by immersing articles in a hot solution of POWER OFF for 10 minutes. After cleaning, rinse thoroughly. Note: add POWER OFF a little at a time to a cold solution only. Avoid adding to hot solutions.

The Quality Chemical Company 
VentureTECH
CORPORATION

10720 Lexington Drive • Knoxville, TN 37932
(865) 966-2532 • 1-800-826-4095 • FAX (865) 675-2532

POWER OFF

HAZARDOUS LIQUID - CONTAINS CAUSTIC SODA.

WARNING: Harmful if Swallowed: Corrosive to mouth, throat, esophagus and stomach. **Avoid Breathing Dust or Mists:** Corrosive to mucous membranes of the respiratory tract. **Avoid Eye Contact: Corrosive to eyes:** Burns eye tissue, cornea and retina. **Avoid Contact With Skin:** Corrosive to skin, causes severe & rapid burns, destructive to tissues on contact. **PERSONAL PROTECTION:** Wash thoroughly after use. Use with adequate ventilation. Chemical type goggles recommended. Impervious rubber or neoprene gloves recommended. **First Aid: INHALATION-**Get to fresh air. **EYES-**Flush with plenty of water for at least 15 minutes. See a physician. **INGESTION-** Do not induce vomiting. If conscious drink plenty of water. Call a physician or poison control center immediately. **SKIN-**Flush with plenty of water. **READ THE MATERIAL SAFETY DATA SHEET (MSDS) BEFORE USING THIS PRODUCT.**

KEEP OUT OF REACH OF CHILDREN

MEMBER
ISSA

HMIS RATING

Health Hazard	0	1	Fire Hazard
3			

0 - None
1 - Slight
2 - Moderate
3 - High
4 - Severe